



AIR CON ENERGY SOLUTIONS LTD

Appliance Number	Description	Class	Inspection Frequency	Test Date	Earth (Ω)	Ins (M Ω)	Leak (mA)	Pass/Fail	Re-Test Date Visual	Earth (Ω)	Ins (M Ω)	Leak (mA)	Pass/Fail
1	Burco 11/100h	11	12 mths 10h	22/5/18	/	200	/	P	22/11/18				
2	LED LIGHT	"	"	"	/	200	/	P	"				
3	contract grille	"	"	"	/	200	/	P	"				
4	"	"	"	"	/	200	/	P	"				
5	"	"	"	"	/	200	/	P	"				
6	Juice Dispenser	"	"	"	/	200	/	P	"				
7	"	"	"	"	/	200	/	P	"				
8	"	"	"	"	/	200	/	P	"				
9	Zumix Mach	"	"	"	0/19	200	/	P	"				

SSy 22/5/18